

LEGACY POOLS USA WARRANTY

13681 Newport Ave Ste 8 144 Tustin CA 92780

This warranty covers the pool only supplied by Legacy Pools USA., which includes the metal superstructure and the polyester reinforced membrane water containment structure. Excluded from this warranty are pumps and electric motors, which are warranted by the manufacturer. To validate this limited warranty, the pool must be registered with Legacy Pools USA, please provide all information requested on the warranty registration form and mail within 4 weeks of purchase to the address above.

*Warranty will be voided when installed improperly on disturbed earth.

This warranty only covers pools sold to authorized dealers by Legacy Pools USA. To obtain performance under this warranty, first contact the dealer from whom the product was purchased. The dealer is charged with the responsibility of determining beyond a reasonable doubt that the defect was one created by the manufacturer. This dealer may correct the defect or arrange to send the damaged/defected component back to Legacy Pools USA, for resealing after acquiring authorization from Legacy Pools USA (freight pre-paid)

Legacy Pools USA Pools, are designed for your swimming enjoyment. Entry and exit from your pool should be by a proper above ground swimming pool ladder.

DO NOT JUMP OR DIVE INTO POOL...EVER!!!

CONDITION OF THIS LIMITED WARRANTY

This limited warranty is extended to the original purchaser and is non-transferable.

This limited warranty covers only the pool supplied by Legacy Pools USA.

This limited warranty provides prorated coverage over a 30-season period. If any defect in workmanship is confirmed by the dealer and Legacy Pools and is reported to the dealer and/or Legacy Pools USA the parts will be re-seamed or re-bonded at the applicable prorated cost. If the local dealer cannot confirm a defect, the purchaser may be required to send the part(s) to Legacy Pools USA at his/her expense and after prior authorization from Legacy Pools USA. The purchaser should clean liner and frame package and send part(s) to Legacy Pools USA. At the sole discretion of Legacy Pools USA there is determination to be a manufacturing defect, the part(s) will be re-seamed with a high frequency welding machine of the same type used to originally seam the liner or re-bonded at Legacy Pools USA option and the applicable freight may be reimbursed. Any part(s) found defected within the first two of the purchase will be re-seamed/re-bonded free of charge. For the next 28 seasons, part(s) found to have a manufacturing defect would be Re-seamed at the then existing manufacturers suggested retail price prorated by applying the percentage for the appropriate season.

3 thru 8 seasons: 50%

9 thru 20 seasons: 75%

21 thru 30 seasons: 80%

Freight for the new or re-bonded part(s) will be billed collect. A cashier's check or money order covering the cost of the new or re-bonded part(s) will be required prior to the shipment from Legacy Pools USA.

No warranty on any pool sold through Garage Sales, E-Bay, Auction Sites, Freight Terminals, or Outlet Stores.

*Dirty Liners will be assessed a 200.00 cleaning fee

Non-warranty Issues

The Use of patio Blocks under the side pipes to prevent sinkage and sand or other substances under the liner rendering the liner unable to adjust to the sinking from the weight of the water

Diving from the side of the pool or other rough play that could cause the separation of the stirrup straps from the pool itself. (We recommend driving a three foot piece of re-bar steel into the ground at the base of the U-pipe

Damaged caused by any outside entity